

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: FUEL SPILL

DATE OCCURRED 10-15-92

DATE REPORTED

TIME OCCURRED 0800

TIME REPORTED

LOCATION(S) OF OCCURRENCE:

GATE 4

REPORTED BY:

PHONE NO(S):

GALVINS

763-0350

SUMMARY:

THE SUPER SONICS BAC 111, 119GA, HAD A FUEL SPILL WHILE AT GATE 4. GALVINS WAS ON THE SCENE LAYING ABSORBENT PADS DOWN WHEN I ARRIVED IN CAR 2. OFFICER DICKIE RESPONDED IN FD#2. WHEN GALVINS WIPED UP AS MUCH AS POSSIBLE, OFFICER DICKIE PROCEEDED WITH CEJER AND A HANDLINE FROM FD#2, AND HOSED THE AREA DOWN. THE SPILL WAS DUE TO PILOT'S ERROR. ACCORDING TO GALVINS, ALL THE FUEL WENT INTO ONE WING, INSTEAD OF BOTH WINGS. AN ESTIMATED 50 GALLONS WAS SPILLED, AND 150 GALLONS OF WATER WAS USED FOR CLEAN UP. ALSO TOWER REPORTED FUEL ON THE TAXIWAY FROM THE BAC 111. UPON INVESTIGATION, BRAVO 7 WILL REQUIRE SOME CLEAN UP, GALVINS WAS CONTACTED.

(SEE REPORT)

OFFICERS:

C. L. Douglas

LEB	CLD	EO	JW
JEB	IE	LGR	FILED
BLC	TUL	CCS	BY
SHD	PCM	JRV	

ACTION: